

Berry Road Lot #12

On January 15, 2002, I met with Jeff & Ricky Minge on the above lot to dig test holes in the soil identified as Montevallo on the soil map. Site #1 is located midway on the lot, Site #2 is located between midway and the back of the lot, Site #3 is located at the back of the lot. Test pits were dug and the results are as follows:

- Site #1: Two test holes were approximately 5.5 feet deep before black chert was encountered. This system should be installed @ 24-30" w/conventional.
- Site #2: Several test pits were dug at approximately 3 feet deep before black chert was encountered. Water then began seeping into the hole through the black chert.
- Site #3: Several test pits were dug at approximately 3 feet deep before black chert was encountered. There was no evidence of water seeping in to hole. The property owner was advised that the only way a system would function in this area would be with a very shallow installation and overflow and/or an aerobic treatment unit, using a conventional gravel system.

Evaluation conducted by:

Kathy Couey-Miller

Environmental Health Specialist II

(7) 749-2270 Cathy Broome

(7) 749-2104

Diane Dawson

Map # 025B

Parcel # 002F

Zoning R-1